

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| | | | | ystem maniter | |
|--|---------------------------|--|------------------------|-----------------------|--------------------|
| This section must be | completed in its entirety | to constitute a v | alid maintenance p | permit. This permit | must be complet |
| <u>prior</u> to perfor | ming maintenance activit | ties and remain o | n-site for the dura | tion of the maintena | nce activity. |
| Date of Maintenance: | 5-5-21 Reason | for Maintenance: | Boutine | | |
| Property Address: 20 | 1098 St Croix Tr | - 5 | Property Owner's N | Name: Lerry ar | nd Kelly Ga |
| Municipality: Ofto | ZIP: <u>5500</u> | Property Ide | entification Number | ·: | 7 |
| Maintenance Permit No | :e6535c22424A | Maintainer Name a | nd License No. Pinl | ov's Environmental Ca | |
| | | | na Electise No. Till | y's Environmental Se | ewer Service/ L16. |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | | Liquid Level of Tank ——— in | | | |
| Sludge and scum measured | | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? | | Sludge + Scum / Liquid Level X 100 | | | |
| ☐ Yes ☐ No (if n | o provide measurements) | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 1. Access used to rem | ove septage: Maintenar | | | | 11 25% of greater |
| | | | enter authorization co | ode) | |
| | urely replaced? Yes | | | | |
| Is there evidence of | tank leakage from a sep | tic, holding, pret | eatment or pump | tank below the oper | ating depth or |
| evidence of damag | ed, cracked, or structura | ally unsound main | tenance hole cove | rs? Yes No | ating depth of |
| _ | Tank | Leaking Out | Leaking In | Cover Damage | |
| | Septic/Holding Tank #1 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Septic/Holding Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐ Ho | ☐ Yes ☐ No | |
| Pretreatn | Pretreatment Tank | Yes No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| n 1 | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | septage were removed? | | | | |
| Tank #1 750 | gal Tank #2 250 | gal Pretreatment | tankga | l Pump Tank | gal |
| . Other information: I | ist any troubleshooting, | minor repairs cor | ducted tank safet | v concerns or other | 501 |
| System Lee | ow for me | us holes | dacted, talk sale | ty concerns, or other | concerns. |
| | | | | | |
| . Location of septage of | isposal: 57. par | 1 | | | |
| | | 19.3 | | I Toy of the last | |
| | Pinky's | Environmental Se | wor Consider Inc | | |
| | i iiiky 3 | | | | |
| | | PO Box 35 | 4 | | |

P: 651-439-4847 License Number: L1673

Afton MN 55001