1. Impact on public health – Compliance component #1 of 5 Compliance criteria: Attached supporting documentation: System discharges sewage to the ☐ Yes* ☒ No Other: ground surface Not applicable System discharges sewage to drain ☐ Yes* ☒ No tile or surface waters. System causes sewage backup into ☐ Yes* ☒ No dwelling or establishment. Any "yes" answer above indicates the system is an imminent threat to public health and safety. Describe verification methods and results: 2. Tank integrity – Compliance component #2 of 5 Compliance criteria: Attached supporting documentation: ☐ Yes* 🛛 No System consists of a seepage pit, Pumped at time of inspection cesspool, drywell, leaching pit, or other pit? Name of maintenance business: Sewage tank(s) leak below their ☐ Yes* ☐ No License number of maintenance business: designed operating depth? Date of maintenance: □ Existing tank integrity assessment (Attach) Date of maintenance 7/8/2021 (mm/dd/yyyy): (must be within three years) If yes, which sewage tank(s) leaks: (See form instructions to ensure assessment complies with Any "yes" answer above indicates the system Minn. R. 7082.0700 subp. 4 B (1)) is failing to protect groundwater. ☐ Tank is Noncompliant (pumping not necessary – explain below) Other: Describe verification methods and results: