DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintena	nce 11-18-15 Reason for	Maintenance:	ta		
Property Address	13670 Partridge F	2N. Property	Owner's Name: 11m	Sulliva	
Municipality: S	murate		5508 Z GEO Cod		
What wa	as done to the system?	Tank Measu	irements (must be com	pleted if tanks NOT pump	ed)
Tank(s) Pumped Sludge and scum measured. Do tanks need to be pumped? Tes No (If no provide measurements)		Liquid Level of Tank Total (Sludge + Scun		= % Sludge & Sc	
1. Access used to remove septage: Maintenance Hole Other (Go to #3 below) * Tank must be pumped if this value is greater than 25%.					
2. If maintenance hole was used, were all covers securely replaced? Yes No please explain					
Explanation:					
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:					
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance					
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit					
Tank#1 Yes No Verificatio Method Used:					
Tank#2 Yes No Verificatio Method Used:					
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence o damaged, cracked, or structurally unsound maintenance hole covers?					
_	Tank	Leaking Out	Leaking In	Cover Damage	_
	Septic/Holding Tank #1	☐ Yes ☐ No	Yes No	Yes No	_
	Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	[Yes No	
	Pretreatment Tank	☐ Yes ☐ No	TYes No	Yes No	-
	Pump Tank	☐ Yes ☐ No	T Yes No	☐ Yes ☐ No	-
6. How many ga	illons of septage were remove	d?			
Tank #1 / Tank #2 Pretreatment Tank Pump Tank					
7. Other inform	ation: List any troubleshootin	g, minor repairs condu	icted, tank safety conce	erns, or other concerns.	
8. Certification:	I hereby certify as a State of M and made the observations, o	r directly supervised oth	ers in the performance o	of this job.	
Maintainer's Name: PINKY'S SEWER SERVICE Maintainer's Address: P.O. Box 354 Afton, MN 55001					
Maintainer's L	icense #: 1673 Maintai	ner's Phone #: 651-439)-4847		
Maintainer's Signature Date: 11-18-15					