DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance	10-22-15 Reason for	Maintenance:	the _		
Property Address:	10150 cakgres	ncenells. Property	Owner's Name: $oldsymbol{\mathcal{B}}_{oldsymbol{c}}$	of Nelson	
Municipality:	Ellwater s	tate 🚹 🗘 Zip Code 🤶	5087 GEO Cod	le/Property I.D. #:	
What was d	one to the system?	Tank Measur	ements (must be com	pleted if tanks NOT pumped)	
Tank(s) Pumped	mongurod	Liquid Level of Tank	in. Sludge Le	evel in. Scum Level i	n.
Sludge and scum measured. Do tanks need to be pumped?		T-t-1 (Student Seums)	/ Liquid Leve	= % Sludge & Scum	*
Yes No (If no provide measurements)		Total (Sludge + Scum)			
1. Access used to ren	nove septage: 🔲 Maintenar	nce Hole Dther (Go	to #3 below)	 Tank must be pumped if this val is greater than 25%. 	ue
2. If maintenance ho	le was used, were all covers se	ecurely replaced? 🔲 Yo	es 🔲 No please expla	in	
Explanation:					
3. If owner refuses to allow a Subsurface Sewage Treatment System (SSTS) to be pumped through the maintenance hole, have them complete and sign the following statement:					
Ι,	(own	er's name), refuse to allo	ow the removal of solid	s and liquids through the maintenar	ıce
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit					
Tank#1 Yes No Verificatio Method Used:					
Tank#2 Yes No Verificatio Method Used:					
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
, damaged, cracke	Tank	Leaking Out	Leaking In	Cover Damage	
Se	eptic/Holding Tank #1	Yes No	☐ Yes ☐ No	Yes No	
Se	eptic/Holding Tank #2	Yes No	☐ Yes ☐ No	☐ Yes ☐ No	
Pı	retreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
P	ump Tank	Yes No	☐ Yes ☐ No	Yes No	
6. How many gallo	ns of septage were removed	17			
Tank #1 1000 Tank #2 1000 Pretreatment Tank Pump Tank					
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
8. Certification: The an	ereby certify as a State of Mir ad made the observations, or	directly supervised othe	rs in the performance o	of this job.	
Maintainer's Nam	e: PINKY'S SEWER SERVICE	Maintainer'	s Address: P.O. Box 354	Afton, MN 55001	
Maintainer's Licer	nse #: 1673 Maintain	er's Phone #: 651-439-	4847		
Maintainer's Sign	ature	-27/	Date:	10-22-15	