## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintena	nce 10 -33-75 Reason f	for Maintenance:	routing		· .	
Property Address	: 9407 otchipme	HAM Property	Owner's Name: St	Unite Propertie	15	
Municipality:	Stillnoter	State Zip Code	GEO Coo	de/Property I.D. #:		
What wa	as done to the system?	Tank Measu	rements (must be con	ppleted if tanks NOT pump	≱d)	
<ul> <li>✓ Tank(s) Pumped</li> <li>☐ Sludge and scum measured.</li> <li>Do tanks need to be pumped?</li> <li>☐ Yes</li> <li>☐ No (If no provide measurements)</li> </ul>		Liquid Level of Tank  Total (Sludge + Scum	in. Sludge L	el = % Sludge & Sci		
1. Access used to	remove septage: Mainte	nance Hole Other (Go	to #3 below)	<ul> <li>Tank must be pumped in its greater than 25%.</li> </ul>	f this value	
2. If maintenance	hole was used, were all cover	s securely replaced?	res No please expl			
Explanation:						
	es to allow a Subsurface Sev e and sign the following stat		(SSTS) to be pumped t	hrough the maintenance ho	ole, have	
l,	(owner's name), refuse to allow the removal of solids and liquids through the maintenance					
hole. I underst	and that removal of solids and	l liquids through other acc	cess points is not consid	lered maintenance.		
<b>4.</b> Is the tank desi	gned as a leaky tank? example	e: seepage pit, cesspool, dry	well, leaching pit			
Tank#1 🔲 Ye	es 🔲 No Verificatio Method	d Used:				
Tank#2 ☐ Ye	es No Verificatio Metho	d Used:				
5. Is there evide	nce of tank leakage from a s cked, or structurally unsoun	eptic, holding, pretreatn	nent or pump tank bel	ow the operating depth or	evidence of	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	Yes No	Yes No	☐ Yes ☐ No		
	Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	ı	
	Pump Tank	☐ Yes ☐ No	Yes No	Yes No		
6. How many ga	llons of septage were remov	ved?				
Tank #1 /500 Tank #2		Pretreatment Tar	Pretreatment Tank		Pump Tank	
7. Other informa	ation: List any troubleshoot	ing, minor repairs condu	cted, tank safety conc	erns, or other concerns.		
8. Certification:	I hereby certify as a State of and made the observations,	or directly supervised oth	ers in the performance	of this job.		
Maintainer's N	lame: PINKY'S SEWER SERVIC	E Maintaine	r's Address: P.O. Box 35	4 ATTON, IVIN 55001		
Maintainer's L	icense #: 1673 Maint	ainer's Phone #: 651-439		2		
Maintainor's C	ignature / //	/	Date: //	b, 2-18		