



Client/ Address:		Rose Steinbach		Legal Description/ GPS:			3503121440004		
Soil parent material(s): (Check all that apply)									
<input type="checkbox"/> Outwash <input type="checkbox"/> Lacustrine <input type="checkbox"/> Loess <input type="checkbox"/> Till <input type="checkbox"/> Alluvium <input type="checkbox"/> Bedrock <input type="checkbox"/> Organic Matter									
Landscape Position: (check one)									
<input type="checkbox"/> Summit <input type="checkbox"/> Shoulder <input checked="" type="checkbox"/> Back/Side Slope <input type="checkbox"/> Foot Slope <input type="checkbox"/> Toe Slope									
Vegetation		Lawn		Soil survey map units 158B		Slope shape		convex - linear	
Elevation:		2.0		Date		07/28/21			
Weather Conditions/Time of Day:									
4:00 pm 92 degrees - partly cloudy									
Observation #/Location:									
See Map									
Observation Type: Auger									
Depth (in)		Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Structure-----	
0-36"		Fine Sand	<35%	10YR 5/4				Shape	Grade
								Single grain	Structureless
36-60"		Fine Sand	<35%	10YR 5/3				Single grain	Structureless
									Loose
									Loose
Comments									
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.									
Shelley Schlomka						4137		7/29/2021	
(Designer/Inspector)						(License #)		(Date)	

Shelley Schlomka
(Signature)