

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	- leted in its antiroty to	constitute a valid	maintenance per	mit. This permit must	be completed
This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 6 8 Reason for Maintenance: 6 Property Owner's Name: Kelli Car San					
Property Address:	TO TO			71011	
Municipality: Mg 🔀	ne ZIP: 550	Property Ident		a 1100 74	78
Maintenance Permit No:	551952298(Ma	aintainer Name and	License No. 5	11/18 CI	<u> </u>
		Tank Measu	rement (must be	completed if tanks NO	T pumped)
Maintenanc	e Performed	SECTION SECTIO	Contract of the Contract of th		
Tank(s) Pumped Sludge and scum measured		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in			
		Sludge + Scum / Liquid Level X 100			
Do tanks need to be	pumped?	I amond if 25% or greater			
☐ Yes ☐ No (if no	- No Stades - Line -				
 Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Ves No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
,-	Tank	Leaking Out	Leaking In	Cover Damage	
-	Septic/Holding Tank #1	☐ Yes No	☐ Yes ☑No	☐ Yes ☐No	
	Septic/Holding Tank #2	☐ Yes ♠No	☐ Yes ੴNo	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes 🕼 No	☐ Yes ♠No	☐ Yes 🗖 No	
1/10/1	of septage were removed gal Tank #2	gal Pretreatmen		gal Pump Tank 300 fety concerns, or othe	gal gal r concerns.