



# OSTP Soil Observation Log

Project ID: v 03.19.15

Client/ Address: John McPherson 2398 Stagecoach Tr N		Legal Description/ GPS: 2202920420004	
Soil parent material(s): (Check all that apply)			
<input type="checkbox"/> Outwash <input type="checkbox"/> Lacustrine <input checked="" type="checkbox"/> Loess <input type="checkbox"/> Till <input type="checkbox"/> Alluvium <input type="checkbox"/> Bedrock <input type="checkbox"/> Organic Matter			
Landscape Position: (check one)			
<input type="checkbox"/> Summit <input type="checkbox"/> Shoulder <input type="checkbox"/> Back/Side Slope <input type="checkbox"/> Foot Slope <input type="checkbox"/> Toe Slope <input type="checkbox"/> Slope shape   Convex - Linear			
Vegetation	Lawn	Soil survey map units	Elevation:
Weather Conditions/Time of Day: Hot Sunny 3:30		49	2.0
Date		08/17/21	
Observation #/Location:		Auger	
See Map			
Depth (in)	Texture	Rock Frag. %	Indicator(s)
0-28"	Silt Loam	<35%	Granular
28-36	Silt Loam	<35%	Granular
36-60"	Loamy Sand	<35%	Granular
Comments			
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.			
Shelley Schломka		4137	8/17/2021
(Designer/Inspector)		(License #)	(Date)

*Shelley Schломka*  
(Signature)