

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a val	id maintenance pe	rmit. This permit n	nust be completed
prior to perfor	ming maintenance activiti	es and remain on-	site for the duratio	on of the maintenar	ice activity.
Date of Maintenance:	6-6-16 Reason 1	for Maintenance: _	Cleaning		
Property Address: <u>/</u> 4	6-6-16 Reason of 390 Kirly Ave	<i>N</i> P	roperty Owner's Na	me: <u>Bi// Du</u>	nbar
Municipality: <u>Hago</u>	ZIP: <u>550</u> 3	Property Ider	tification Number:		
	0: <u>46208, 2954</u> M				2428
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b		Sludge + Scum / Liquid Level X 100			
oximes Yes $oxdot$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers see Is there evidence of 	nove septage: Maintenar curely replaced? Yes of f tank leakage from a sep ged, cracked, or structura	□ No tic, holding, pretr	eatment or pump t	ank below the ope	rating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 1000	gal Tank #2	gal Pretreatmen	t tankga	al Pump Tank <u>3</u> 0	OO gal
5. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safe	ty concerns, or oth	er concerns.
6. Location of septage	e disposal:				