


OSTP Soil Observation Log



Project ID: v 03.19.15

Client/ Address:		Jody Antoniou - 7430 Lamar Ave		Legal Description/ GPS:		1202721230004	
Soil parent material(s): (Check all that apply)							
<input type="checkbox"/> Summit		<input type="checkbox"/> Shoulder		<input type="checkbox"/> Back/Side Slope		<input type="checkbox"/> Toe Slope	
<input type="checkbox"/> Outwash		<input type="checkbox"/> Lacustrine		<input checked="" type="checkbox"/> Loess		<input type="checkbox"/> Bedrock	
<input type="checkbox"/> Alluvium		<input type="checkbox"/> Till		<input type="checkbox"/> Organic Matter			
Landscape Position: (check one)				Slope shape			
<input checked="" type="checkbox"/> Lawn		<input type="checkbox"/> Summit		<input type="checkbox"/> Foot Slope		<input type="checkbox"/> Convex	
Vegetation		Soil survey map units 49 & 49B		Slope%		Elevation:	
Weather Conditions/Time of Day:		3:30 - hot humid		Date		08/24/21	
Observation #/Location:				Observation Type:			
Middle of property				Auger			
Depth (in)		Texture		Matrix Color(s)		Mottle Color(s)	
0-32"		Silt Loam		7.5YR 4/6		Redox Kind(s)	
32-60"		Silt Loam		10YR 5/6		Indicator(s)	
Rock Frag. %		<35%		Shape		Structure	
				Platey		Grade	
				Platey		Consistence	
				Weak		Friable	
				Weak		Friable	
Comments							
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.							
Designer/Inspector				4137		8/24/2021	
Shelley Schlomka				(License #)		(Date)	
 (Signature)							