## Impact on public health – Compliance component #1 of 5 Compliance criteria: Attached supporting documentation: ☐ Yes\* 🛛 No System discharges sewage to the ☐ Other: ground surface ☐ Not applicable System discharges sewage to drain ☐ Yes\* ☒ No tile or surface waters. System causes sewage backup into ☐ Yes\* 🛛 No dwelling or establishment. Any "yes" answer above indicates the system is an imminent threat to public health and safety. Describe verification methods and results: 2. Tank integrity – Compliance component #2 of 5 Compliance criteria: Attached supporting documentation: System consists of a seepage pit, Yes<sup>⋆</sup> No Pumped at time of inspection cesspool, drywell, leaching pit, or other pit? Name of maintenance business: Sewage tank(s) leak below their Yes\* □ No License number of maintenance business: designed operating depth? Date of maintenance: ☐ Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (must be within three years) If yes, which sewage tank(s) leaks: Only one tank Any "yes" answer above indicates the system (See form instructions to ensure assessment complies with Minn. R. 7082.0700 subp. 4 B (1)) is failing to protect groundwater. ☐ Tank is Noncompliant (pumping not necessary – explain below) Other: Describe verification methods and results: PROBED TANK -DIRT BOTTOM