



Client/ Address:		1243 Neal Ave S - Dave Arnt		Legal Description/ GPS:		8.0282E+11	
Soil parent material(s): (Check all that apply)							
<input type="checkbox"/> Summit		<input checked="" type="checkbox"/> Shoulder		<input type="checkbox"/> Back/Side Slope		<input type="checkbox"/> Toe Slope	
<input type="checkbox"/> Outwash		<input type="checkbox"/> Lacustrine		<input type="checkbox"/> Loess		<input type="checkbox"/> Till	
<input type="checkbox"/> Alluvium		<input type="checkbox"/> Bedrock		<input type="checkbox"/> Organic Matter			
Landscape Position: (check one)				Slope shape		Convex Convex	
Vegetation		grass		Soil survey map units 155C		Elevation:	
Weather Conditions /Time of Day:		Hot - Sun 9:00 am		Date		05/20/21	
Observation #/Location:		See Map		Observation Type:		Auger	
Depth (in)		Texture		Rock Frag. %		Matrix Color(s)	
Mottle Color(s)		Redox Kind(s)		Indicator(s)		Shape	
Consistency		Structure		Grade		Consistence	
0-12"	Sand	<35%	10YR 3/4			GRANULAR W	loose
12-36"	Coarse Sand	<35%	10YR 3/6			GRANULAR W	loose
36-60"	Sand	<35%	10YR 4/6			GRANULAR W	loose
Comments							
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.							
Shelley Schlomka		(Designer/Inspector)		4137		(License #)	
		(Signature)				(Date)	
						8/20/2021	