3.	Other compliance conditions – Compliance component #3 of 5		
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured?  ☐ Yes* ☑ No ☐ Unknown		
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety *Yes to 3a or 3b - System is an imminent threat to public health and safety.	y? ☐ Yes* 🖾 No ☐ Unknown	
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes* ☑ No	
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes* ☒ No	
	*Yes to 3c or 3d - System is failing to protect groundwater.		
	Describe verification methods and results:		
	·		
	Attached supporting documentation:   Not applicable		
		and the second s	
4.	Operating permit and nitrogen BMP* - Compliance component #4 o	f 5 🛭 Not applicable	
	Is the system operated under an Operating Permit?	f "yes", A below is required	
	Is the system required to employ a Nitrogen BMP specified in the system design?   Yes   No I	f "yes", B below is required	
	BMP = Best Management Practice(s) specified in the system design		
	If the answer to both questions is "no", this section does not need to be completed	<b>1</b> .	
	Compliance criteria:	<del>.</del>	
	No. of the state o		
	b. Is the required nitrogen BMP in place and properly functioning?   Yes  No		
	Any "no" answer indicates noncompliance.		
	Describe verification methods and results:		
	Americal companion decompanies — — — — — — — — — — — — — — — — — — —		
	Attached supporting documentation:		

https://www.pca.state.mn.us wq-wwists4-31b • 1/11/21