

OSTP Soil Observation Log



Project ID: v 03.19.15

Client/ Address:		Tom Ellis - 5590 Garden Court		Legal Description/ GPS:		3202821420003	
Soil parent material(s): (Check all that apply)							
<input type="checkbox"/> Summit		<input checked="" type="checkbox"/> Shoulder		<input type="checkbox"/> Lacustrine		<input type="checkbox"/> Bedrock	
<input type="checkbox"/> Outwash		<input type="checkbox"/> Till		<input type="checkbox"/> Alluvium		<input type="checkbox"/> Organic Matter	
Landscape Position: (check one)							
<input type="checkbox"/> Summit		<input checked="" type="checkbox"/> Shoulder		<input type="checkbox"/> Back/Side Slope		<input type="checkbox"/> Toe Slope	
<input type="checkbox"/> Lawn		Soil survey map units 155D		Slope shape		Convex Convex	
Vegetation				Slope%		20.0	
Elevation:				Date		08/30/21	
Weather Conditions/Time of Day:		4:00 - Sun warm		Observation Type:		Auger	
Observation #/Location:		See Map		Indicator(s)		Structure-----	
Depth (in)		Texture		Matrix Color(s)		Mottle Color(s)	
0-12"		Loamy Sand		<35% 7.5YR 4/4		Redox Kind(s)	
12-60"		Sandy Loam		<35% 7.5YR 4/6		Shape	
				Granular		Weak	
				Granular		Weak	
						Consistence	
						Loose	
						Loose	
Comments							
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.							
Shelley Schlomka				4137		08/30/2021P	
(Designer/Inspector)		(Signature)		(License #)		(Date)	