ess Name: SS Septic Solutions, LLC	-	Date:	9/14/2021
pact on public health – C	ompliance com	ponent #1 of 5	
Compliance criteria:	-	Attached supporting documentation	on:
System discharges sewage to the ground surface	☐ Yes* ☒ No	☐ Other: ☐ Not applicable	
System discharges sewage to drain tile or surface waters.	☐ Yes* ☒ No	_	
System causes sewage backup into dwelling or establishment.	☐ Yes* ☒ No		
Any "yes" answer above indicates imminent threat to public health ai			
Describe verification methods and	i results:		
nk integrity – Compliance	.component #7	of F	
<b>nk integrity</b> – Compliance	component #2	? of 5	
	component #2		
Compliance criteria:	component #2	of 5 Attached supporting documentation	on:
Compliance criteria: System consists of a seepage pit,	component #2		on:
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit,		Attached supporting documentation  Empty tank(s) viewed by inspector	on:
Compliance criteria: System consists of a seepage pit,		Attached supporting documentation	on: Meyers
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:	Meyers
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their		Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busin	Meyers
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:	Meyers
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	☐ Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business Date of maintenance:	Meyers ness: 9/14/2021
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	☐ Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busin	Meyers ness: 9/14/2021
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	☐ Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines Date of maintenance:  Existing tank integrity assessment (Attached support of the company of	Meyers ness: 9/14/2021
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?	☐ Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance businest Date of maintenance:  Existing tank integrity assessment (Attached support of maintenance)	Meyers ness: 9/14/2021 tach)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	☐ Yes* ⊠ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance businest Date of maintenance:  Existing tank integrity assessment (Attached support of maintenance)	Meyers ness: 9/14/2021
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:	☐ Yes* ☑ No	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance  (mm/dd/yyyy):  (must be with	Meyers less: 9/14/2021 tach) hin three years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicates	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ tes the system	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines business busi	Meyers less: 9/14/2021 tach) hin three years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ tes the system	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the minus of the maintenance)  (See form instructions to ensure assessment)  Minn. R. 7082.0700 subp. 4 B (1))	Meyers ness: 9/14/2021 tach) hin three years) ssment complies v
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicates	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ tes the system	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the minus of the maintenance)  (See form instructions to ensure assessment)  Minn. R. 7082.0700 subp. 4 B (1))	Meyers ness: 9/14/2021 tach) hin three years) ssment complies v
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicates	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ tes the system	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance busines busines of maintenance:  Existing tank integrity assessment (Attached July 1999):  (See form instructions to ensure assessment in the maintenance of mai	Meyers ness: 9/14/2021 tach) hin three years) ssment complies v
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicates	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ tes the system	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the minus of the maintenance)  (See form instructions to ensure assessment)  Minn. R. 7082.0700 subp. 4 B (1))	Meyers  9/14/2021  tach)  hin three years)  ssment complies v  essary – explain bel
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indic is failing to protect groundwate	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ tes the system er.	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the complete of the complet	Meyers  9/14/2021  tach)  hin three years)  ssment complies v  essary – explain bel
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indicates	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ tes the system er.	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the complete of the complet	Meyers  9/14/2021  tach)  hin three years)  ssment complies v  essary – explain bel
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indic is failing to protect groundwate	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ tes the system er.	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the complete of the complet	Meyers  9/14/2021  tach)  hin three years)  ssment complies v  essary – explain bel
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indic is failing to protect groundwate	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ tes the system er.	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the complete of the complet	Meyers  9/14/2021  tach)  hin three years)  ssment complies v  essary – explain bel
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indic is failing to protect groundwate	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ tes the system er.	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the complete of the complet	Meyers  9/14/2021  tach)  hin three years)  ssment complies v  essary – explain bel
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indic is failing to protect groundwate	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ tes the system er.	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the complete of the complet	Meyers  9/14/2021  tach)  hin three years)  ssment complies v  essary – explain bel
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indic is failing to protect groundwate	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ tes the system er.	Attached supporting documentation  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attached)  Date of maintenance (mm/dd/yyyy): (must be with the complete of the complet	Meyers  9/14/2021  tach)  hin three years)  ssment complies v  essary – explain bel