

OSTP Soil Observation Log

Project ID:

v 03.19.15



Client / Address: Deanna Lowe 14220 50th Street South

Legal Description / GPS:

2802820330001

Soil parent material(s): (Check all that apply)

- Summit Shoulder Back/Side Slope Foot Slope Toe Slope Outwash Lacustrine Loess Till Alluvium Bedrock Organic Matter

Landscape Position: (check one)

- Summit Shoulder Back/Side Slope Foot Slope Toe Slope Slope shape

Vegetation

grass

Soil survey map units 174C

Slope%

Elevation:

Weather Conditions/Time of Day:

Sun - 4:30

Date

09/27/21

Observation #/Location:

See Map

Observation Type:

Auger

Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Structure		
							Shape	Grade	Consistence
0-18"	Silt Loam	<35%	7.5YR 3/3				Blocky	Moderate	Friable
18-32"	Clay Loam	<35%	7.5YR 3/4				Blocky	Moderate	Friable
32-44"	Sandy Loam	<35%	10YR 4/6				Granular	Weak	Loose
44-60"	Sand	<35%	7.5YR 4/4				Granular	Weak	Loose

Comments

I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.

Shelley Schlomka

4137

9/27/2021

(Designer/Inspector)

(Signature)

(License #)

(Date)