DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 5/34/16 Reason to	or Maintenance: <u> </u>	OU TINE		
Property Address: 13740 OAIChi	HRd N Prope	rty Owner's Name:	ul MACK	<u>.</u>
Municipality: Scandia	State M Zip Code	55 073 GEO Code	e/Property I.D. #:	
What was done to the system?	Tank Measurements (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of Tan	k in. Sludge Le	vel in. Scum Level	in.
Sludge and scum measured.	liciquid Level of Tail	iii. Sludge Le		
Do tanks need to be pumped? Yes No (If no provide measurement)	Total (Sludge + Scu	im)/ Liquid Level	= % Sludge & Sco	ım*
1. Access used to remove septage: Mainten	ance Hole 🔲 Other (0	Go to #3 below)	* Tank must be pumped it is greater than 25%.	fthis value
2. If maintenance hole was used, were all covers	securely replaced?	Yes No <i>please explai</i>	-	
Explanation:				
3. If owner refuses to allow a Subsurface Sewa	-	(SSTS) to be pumped thi	rough the maintenance ho	ole, have
them complete and sign the following state			,	
			and liquids through the ma	iintenance
hole. I understand that removal of solids and	•	•	red maintenance.	
4. Is the tank designed as a leaky tank? <i>example</i> :	seepage pit, cesspool, di	ywell, leaching pit	-	_
Tank#1 Tyes XNo Verificatio Method	Used:			
Tank#2 Yes No Verificatio Method	Used:	•		
5. Is there evidence of tank leakage from a se		ment or pump tank belo	w the operating depth or o	evidence of
damaged, cracked, or structurally unsound	maintenance hole co	vers?		
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes J No	Yes N o	
Septic/Holding Tank #2	Yes No	Yes No	Yes No	
Pretreatment Tank	Yes No	Yes No	Yes No	
Pump Tank	Yes KNo	Yes X No .	Yes # No	
6. How many gallons of septage were remove	ed?			•
Tank #1 1500 Tank #2	Pretreatment Ta	nk Pur	mp Tank	-
7. Other Information: List any troubleshooting	g, minor repairs cond	ucted, tank safety concer	ns, or other concerns.	:
8. Certification: I hereby certify as a State of Mi and made the observations, or	r directly supervised oth	ners in the performance of	this job.	
Maintainer's Name: Ross' Sewer Service	Maintaine	er's Address: 9288 County	Rd 5 NE North Branch, MN 5	5056
Maintainer's License #: L3448 Maintai	ner's Phone #: 651-67		*	
Maintainer's Signature		Date: <u>5</u>	124/16	