

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

System Location	
Address 13040 Ingersoll Ave	Telephone Number 612-205-757
City Hugo State	ZIP 5503% Property ID No./GEO Code
Owner Jennifer Klock Pumping Date 8-26-21	
V 1656-11553 Contractor	
Maintainer North Side Septie Sve LCC MPCA License No. 930 Telephone Number 743-444 7898	
What was done to the system?	Report Liquid Capacity in Gallons
Tank(s) Pumped	Tank 1: /500 Pumped Tank 2:/000 Pumped
Sludge and scum measured.	Tank 3: 900 Pumped Tank 4: Pumped
Do tanks need to be pumped?	
Yes No (If no provide measurements below)	Total Gallons Pumped:
Visual Inspection (note any problems with the system):	NOTE: This does not serve as a compliance inspection.
2nd 1000 septic . Tank was not pumped.	
O"sum effluent fol	d an almost
4" Slodge	RECEIVED
4)" /iquich	OCT 1 4 2021
* 5	The state of the s
9% solids northsideseptic agmail, com Jake Carpenter	
*Tank Measurements-Use Only If Tank(s) Were NOT Pumped	
Liquid Level of Tank (Distance from Invert of outlet pipe to bottom of tank) 42 in. 15th Tank	
Sludge Level 12 in. + Scum Level 4 in. = Total Sludge and Scum Level 14	
Total Sludge and Scum Level/ Liquid Level	= Percent Sludge and Scum in Tank 38 %
Scum Layer  Effluent  Sludge Layer	*Tanks must be pumped if either of the following conditions exist:  1. The top of the sludge layer is less than 12 inches from the bottom of the outlet baffle; or  2. Total sludge and scum volume is greater than 25 percent of the tank's liquid capacity.
Signature Date	8-24-2/ Reset Form