Compliance criteria:		Attached supporting documentation:	
System discharges sewage to the ground surface	☐ Yes* ☑ No	☐ Other: ☐ Not applicable	
System discharges sewage to drain tile or surface waters.	☐ Yes* ⊠ No		
System causes sewage backup into dwelling or establishment.	☐ Yes* ⊠ No		
Any "yes" answer above indicates imminent threat to public health at			
Describe verification methods and	l results:		
ank integrity. Compliance		-fr	
<b>ınk integrity</b> – Compliance	component #2	of 5	
<b>ink integrity</b> — Compliance Compliance criteria:	component #2		ation:
Compliance criteria:		Attached supporting documents	
Compliance criteria:  System consists of a seepage pit,	e component #2		
Compliance criteria:		Attached supporting documents	
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ☒ No	Attached supporting documents  Empty tank(s) viewed by inspector  Name of maintenance business:	Meyers
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their		Attached supporting documents  ⊠ Empty tank(s) viewed by inspector	Meyers usiness:
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ☒ No	Attached supporting documents  Empty tank(s) viewed by inspector  Name of maintenance business:	Meyers
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	☐ Yes* ☒ No	Attached supporting documents  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business business of maintenance business.	Meyers usiness: 10/14/2021
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	☐ Yes* ☒ No	Attached supporting documents  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business of maintenance:  Existing tank integrity assessment	Meyers usiness: 10/14/2021
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?	☐ Yes* ☒ No	Attached supporting documents  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business of maintenance:  Existing tank integrity assessment  Date of maintenance	Meyers usiness: 10/14/2021 (Attach)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:	☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documents  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business of maintenance:  Existing tank integrity assessment  Date of maintenance	Meyers usiness: 10/14/2021
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indice	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documents  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment  Date of maintenance (mm/dd/yyyy):  (See form instructions to ensure as	Meyers usiness: 10/14/2021 (Attach) within three years)
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documents  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment  Date of maintenance (mm/dd/yyyy):  (See form instructions to ensure as Minn. R. 7082.0700 subp. 4 B (1))	Meyers  usiness:  10/14/2021  (Attach)  within three years)  ssessment complies w
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indice	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documents  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment  Date of maintenance (mm/dd/yyyy):  (See form instructions to ensure as	Meyers  usiness:  10/14/2021  (Attach)  within three years)  ssessment complies w
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indice	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documents  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  License number of maintenance business:  Existing tank integrity assessment  Date of maintenance (mm/dd/yyyy):  (See form instructions to ensure as Minn. R. 7082.0700 subp. 4 B (1))  Tank is Noncompliant (pumping not	Meyers  usiness:  10/14/2021  (Attach)  within three years)  ssessment complies w
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indice	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No eates the system	Attached supporting documents  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  License number of maintenance business:  Existing tank integrity assessment  Date of maintenance (mm/dd/yyyy):  (See form instructions to ensure as Minn. R. 7082.0700 subp. 4 B (1))  Tank is Noncompliant (pumping not	Meyers  usiness:  10/14/2021  (Attach)  within three years)  ssessment complies we necessary – explain belonger