		Date: 10/9/2021
pact on public health - C	ompliance com	ponent #1 of 5
Compliance criteria:		Attached supporting documentation:
System discharges sewage to the pround surface	☐ Yes* ⊠ No	☐ Other: ☐ Not applicable
System discharges sewage to drain le or surface waters.	☐ Yes* ☒ No	
System causes sewage backup into welling or establishment.	☐ Yes* ⊠ No	
ny "yes" answer above indicates mminent threat to public health a		
Describe verification methods and	l results:	
nk integrity – Compliance	component #2	
Compliance criteria:		Attached supporting documentation:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	component #2	
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ☑ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,		Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☑ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☑ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☑ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance:
Compliance criteria: System consists of a seepage pit, sesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ ates the system	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance 10/9/2021
Compliance criteria: System consists of a seepage pit, sesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ ates the system	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (See form instructions to ensure assessment com
Compliance criteria: System consists of a seepage pit, sesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ ates the system	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance 10/9/2021 (mm/dd/yyyy): (must be within three years) (See form instructions to ensure assessment community. Minn. R. 7082.0700 subp. 4 B (1))