

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	6.79.71	20 24/2 20 24/2	D. J.			
Date of Maintenance	Reason	for Maintenance:	Routine			
Property Address:	11535 218 St	N .	Property Owner's N	lame: Bolla Tam	my Dochmin	
Municipality: Scar	Idos ZIP: 550	Property Ide	ntification Number	:	/	
Maintenance Permit	No: p3150 = 24684 N	Maintainer Name a	nd License No. Smi	lie's Sewer Service/I	2/28	
mameeriance remine	110.	iameanier name a	id Electise No. Sim	tie 3 Sewer Service/L	-2420	
Mainten	ance Performed	Tank Meas	surement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped			Tank in			
☐ Sludge and scum	measured	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to			Sludge + Scum / Liquid Level X 100   = % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if	f no provide measurements)	- % studge & sc	um ra	nks must be pumped	i ii 25% or greater	
1 Access used to re	emove septage:   Maintenar	So Hole Other (				
		,	enter authorization c	ode)		
The state of the s	ecurely replaced? Yes					
3. Is there evidence	of tank leakage from a sep naged, cracked, or structura	tic, holding, pret	eatment or pump	tank below the ope	rating depth or	
evidence of dan	r	atty urisound main	terrance note cove	Yes No		
	Tank	Leaking Out	Leaking In	<b>Cover Damage</b>		
	Septic/Holding Tank #1	☐ Yes 🗖 No	☐ Yes ►No	☐ Yes ☒No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4 How many gallone	s of septage were removed?					
	gal Tank #2		t tank g	al Pump Tank	gal	
5. Other information	n: List any troubleshooting,	minor repairs co	nducted, tank safe	ety concerns, or oth	er concerns	
	,	or repairs co	radeted, turnt burt	ety contectnis, or oth	er concerns.	
			1 1			
6. Location of septage disposal:		Lund Applied				

Smilie's Sewer Service **PO BOX 100** Scandia, MN 55073 License# 2428 P: 651-433-3934

Maintenance activities must be reported to the Department within 90 days.