

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

prior to performing maintenance activity	to constitute a v	alid maintenance	permit. This permit	must be completed
prior to performing maintenance activity			ation of the maintena	ince activity.
Date of Maintenance: 6-14-16 Reason	for Maintenance:	Routine		
Property Address: 15320 113 The 3th	N	Property Owner's	Name: Diane	Kren 7
Municipality: Stilwater ZIP: 550	Property Id	entification Numbe	er:	
Maintenance Permit No: 10874p 3000 M				ewer Service/L1673
Maintenance Performed	Tank Mea	surement (must b	pe completed if tanks	NOT pumped)
Tank(s) Pumped	Liquid Level of Tank in			
\square Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: Maintenan Were all covers securely replaced? Yes Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structura 	No	reatment or num	n tank holow the one	rating depth or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?			7.	
Tank #1 1500 gal Tank #2	gal Pretreatmen	t tank g	gal Pump Tank	gal
Other information: List any troubleshooting, r	minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns
exposed munholl but was a l	vedge cou	er that is	ill not come	act of
top of tank pumped through	6" pipe	coming out	of manhole	
6. Location of septage disposal:				

Maintenance activities must be reported to the Department within 90 days.