Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entiret	y to constitute a va	lid maintenance p	permit. This permit m	nust be complete	
<u>prior</u> to performing maintenance activ	ities and remain on	-site for the dura	tion of the maintenan	ce activity.	
Date of Maintenance: 7-28-21 Reaso	n for Maintenance:	Kartue			
Property Address: 10690 Quary	y Ave Do	Property Owner's N	lame: Gloria	Sell	
Municipality: Stillwater zip: 55	Property Idea	ntification Number	:		
17/7 777					
3	married Name at	id License No. Pini	ky's Environmental Sev	ver Service/ L167	
Maintenance Performed	Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
\square Yes \square No (if no provide measurements) = % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: \Box Maintena	ance Hole Other (e				
3. Is there evidence of tank leakage from a se evidence of damaged, cracked, or structur Tank	rally unsound maint	enance hole cove	rs? Yes No Cover Damage	ting depth or	
Septic/Holding Tank #1	☐ Yes ☑ No				
		Yes No	Yes No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No			
	65 _ 110	□ 162 □ NO	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No			
4. How many gallons of septage were removed Tank #1 gal Tank #2	☐ Yes ☐ No ? _gal Pretreatment	Yes No	☐ Yes ☐ No	gal concerns.	
4. How many gallons of septage were removed	☐ Yes ☐ No ? _gal Pretreatment	Yes No	☐ Yes ☐ No	gal concerns.	
Tank #1 Occ gal Tank #2	Yes No ? _gal Pretreatment , minor repairs cond	Yes No tankga	Yes No Pump Tank y concerns, or other	concerns.	
4. How many gallons of septage were removed Tank #1 gal Tank #2	Yes No ? _gal Pretreatment , minor repairs cond	Yes No tankga	Yes No Pump Tank y concerns, or other	concerns.	

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673