Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entiret	y to constitute a v	alid maintenance	pormit This			
<u>prior</u> to performing maintenance activ	ities and remain o	n-site for the dura	tion of the mainten	must be completed		
Date of Maintenance: 7-26-21 Reaso	n for Maintenance:	Rentun	tion of the maintena	ance activity.		
		Property Owner's	O soil	20 42 - 0 0		
Municipality: (A) F T ZIP: 55	CV7 Proporty Id	Property Owner's	Name:	egerstron		
Maintenance Pormit No. 18 UK 277776	Property Id	entification Numbe	r:			
Maintenance Permit Noc18645n23228	Maintainer Name a	and License No. Pin	ky's Environmental Se	ewer Service/ L1673		
Maintenance Performed	Maintenance Performed Tank Measure			urement (must be completed if tanks NOT pumped)		
Tank(s) Pumped	THE RESERVE OF THE PARTY OF THE	Liquid Level of Tank — in				
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in					
Do tanks need to be pumped?	Sludge + Scum					
☐ Yes ☐ No (if no provide measurements)	= % Sludge & So	= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to remove septage: Maintena	ance Hole Other	enter authorization o	oda)	25% of greater		
2. Were all covers securely replaced? Yes		enter additionization c	ode)			
3. Is there evidence of tank leakage from a sep						
evidence of damaged, cracked, or structur	ally unsound mair	tenance hole cove	tank below the oper	ating depth or		
		- Total Cove	15: 🗆 165 🗆 140			
Tank	Leaking Out	Leaking In	Cover Damage			
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
4. How many gallons of septage were removed	?					
Tank #1 <u>/ 7 00</u> gal Tank #2	_gal Pretreatment	tankga	al Pump Tank	σal		
5. Other information: List any troubleshooting,	minor repairs cor	ducted, tank safet	v concerns, or other	Concerns		
Manhole under land segging Cours t	The state of the s			concerns.		
6. Location of septage disposal: wwfp))		
/						
Pinky's	s Environmental Se	wer Service Inc.				
	PO Box 35					
	Afton MN 550					

Maintenance activities must be reported to the Department within 90 days.