

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety prior to performing maintenance activit			The state of the s
Date of Maintenance: 722-21 Reason		on or the maintena	nice activity.
		Vacilia	Milla a
Property Address: 2699 Over COV	Property Owner's N	ame: WCCCL	Miller +
Municipality: Shllucter zip: SS	Property Identification Number	11 11	Greg Kni
Maintenance Permit No: S6913 v 23765	Maintainer Name and License No. Pink	y's Environmental Se	ewer Service/ L167
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)		
Tank(s) Pumped	Liquid Level of Tank ——— in		
\square Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in		
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100		
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater		
evidence of damaged, cracked, or structur Tank	Leaking Out Leaking In	rs? Yes No Cover Damage	
Septic/Holding Tank #1	☐ Yes ☑No ☐ Yes ☑No	☐ Yes ☑ No	
Septic/Holding Tank #2	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed Tank #1 15 cc gal Tank #2	? _gal Pretreatment tankg	al Pump Tank	gal
5. Other information: List any troubleshooting 6. Location of septage disposal:			
•		THE RESTRICTED OF THE PARTY OF	

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673