## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT 24444a25229

Date of Maintenance 10/29/21 Reason	for Maintenance:		
Date of Maniteriance 197414			D W
Property Address: 2819 Dry Avel	Proper	ty Owner's Name:	7
Municipality: Lukelmo	State Zip Code	GEO Coo	de/Property I.D. #:
What was done to the system?	TankiMea	nrements(musub@@)	pleted if tanks NOT pumped)
Tank(s) Pumped	Liquid Level of Tan	in. Sludge L	evel in. Scum Level in.
Sludge and scum measured.			Of Chadas & Carry
Do tanks need to be pumped?  Yes No (If no provide measuremen	Total (Sludge + Scu	m)/ Liquid Lev	el = % Sludge & Scum
1. Access used to remove septage: Mainte	nance Hole Other (C	io to #3 below)	<ul> <li>* Tank must be pumped if this value is greater than 25%.</li> </ul>
2. If maintenance hole was used, were all cover	s securely replaced? 🛭 💆	Yes 🔲 No <b>please expl</b> e	ain
Explanation:			
3. If owner refuses to allow a Subsurface Sev them complete and sign the following state	vage Treatment System lement:	(SSTS) to be pumped ti	hrough the maintenance hole, have
l, (owner's name), refuse to allow the removal of solids and liquids through the maintenance			
hole. I understand that removal of solids and			ered maintenance.
4. Is the tank designed as a leaky tank? example	e: seepage pit, cesspool, di	ywell, leaching pit	
Tank#1 Yes Verificatio Method	d Used:		
Tank#2 Yes No Verificatio Method	d Used:		
5. Is there evidence of tank leakage from a s damaged, cracked, or structurally unsoun	eptic, holding, pretreat d maintenance hole co	ment or pump tank belovers?	ow the operating depth or evidence
Tank	Leaking Out	Leaking In	Cover Damage
Septic/Holding Tank #1	Yes No	Yes No	Yes No
Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	Yes No
Pretreatment Tank	Yes No	☐ Yes ☐ No	Yes No
Pump Tank	Yes No	Yes No	Yes No
6. How many gallons of septage were remove	red?		
Tank #1 Tank #2	T T C LI COLLINO TO		ump Tank 250
7. Other information: List any troubleshoot	ing, minor repairs cond	ucted, tank safety conce	erns, or other concerns.
8. Certification: I hereby certify as a State of and made the observations,	Minnesota certified SSTS or directly supervised ot	Maintainer that I persona hers in the performance o	lly conducted the work of this job.
Maintainer's Name: Olson's Sewer Service,			s Street NE, Forest Lake, MN
Maintainer's License #: 216 Maint	ainer's Phone #: 651-46	4-2082	