## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

## **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT

Date of Maintena	nce MtolZ Reason	n for Maintenance:	Ullek25	642		
Property Address:	9856-51sts	Prop	erty Owner's Name:	Kent Loberts		
Municipality:	ake Elmo	State Zip Cod	e GEO	Code/Property I.D. #:		
. What wa	s done to the system?	Tank Me	asurements (must be	completed if tanks NOT pum	iped)	
Tank(s) Pumped		Liquid Level of Tar	in Clud	in Court	el in.	
Sludge and scum measured.		Liquid Level Of Tai	ik in. Sludg	ge Level in. Scum Leve		
Do tanks need to be pumped?  Yes No (If no provide measurements)		Total (Sludge + Sc	Total (Sludge + Scum) / Liquid Level = % Sludge & Scum			
1. Access used to r	emove septage: 😥 Maint	enance Hole Other (	Go to #3 below)	* Tank must be pumped	d if this value	
2. If maintenance I	hole was used, were all cove	rs securely replaced?	Yes □No <b>please e</b>	is greater than 25%. x <b>plain</b>		
Explanation:						
3. If owner refuse them complete	s to allow a Subsurface Se and sign the following sta	wage Treatment Syster tement:	n (SSTS) to be pumpe	d through the maintenance	hole, have	
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance						
hole. I understa	nd that removal of solids an			•		
4. Is the tank desig	ned as a leaky tank? exampl	e: seepage pit, cesspool, d	rywell, leaching pit			
Tank#1 Yes	No Verificatio Metho	d Used:				
Tank#2 Tes	No Verificatio Metho	d Used:				
5. Is there evidence damaged, crack	ce of tank leakage from a s ced, or structurally unsoun	eptic, holding, pretreated maintenance hole co	tment or pump tank it vers?	elow the operating depth o	r evidence of	
	Tank	Leaking Out	Leaking In	Cover Damage		
-	Septic/Holding Tank #1	Yes No	Yes No	T Yes O No	•0	
-	Septic/Holding Tank #2	Yes No	Yes No	Yes No	et.	
	Pretreatment Tank	Yes No	Yes No	Yes No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	<b>b</b> )	
6. How many gallo	ons of septage were remov	red?			*)	
Tank #1 925 Tank #2 925 Pretreatment Tank Pump Tank						
7. Other informati	on: List any troubleshooti	ng, minor repairs cond	ucted, tank safety cor	cerns, or other concerns.		
	hereby certify as a State of N nd made the observations, o					
Maintainer's Nan	ne: Olson's Sewer Service, I	nc. Maintaine	er's Address: 17638 Lyc	ns Street NE, Forest Lake, MN		
Maintainer's Lice	ense #: 216 Mainta	iner's Phone #: 651-46	4-2082			
Maintainer's Sigr	nature JA		Date:	11-10-21		