Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must	he completed in the			- your married		
prior to per	be completed in its entirety	y to constitute a	alid maintenance	permit. This permit	must be completed	
)	ities and remain o	n-site for the dura	tion of the maintena	nce activity.	
Date of Maintenance	e: /- /- Reason	n for Maintenance:	Routine			
Property Address:	9180 Stonebild	GETIN	Property Owner's	Name: Dan Son	bu Ha	
Municipality: 5/1/	luater ZIP:550	8 2-Property Id	entification Numbo	r.	TILLE	
Maintenance Permit	Nog0159n23182	Maintainer Namo	and Linear No. Bi			
		marreamer Name	and License No. Pin	ky's Environmental Se	wer Service/ L1673	
Mainter	nance Performed	Tank Mea	asurement (must be	e completed if tanks	NOT pumped)	
Tank(s) Pumped			Tank Measurement (must be completed if tanks NOT pumped) Liquid Level of Tank — in			
Sludge and scum measured		Sludge Level in Tank in Sound in				
Do tanks need to be pumped? Yes No (if no provide measurements)		Sludge + Scum / Liquid Level X 100				
		= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to re	emove septage: Maintena			must be pumped	or greater	
2. Were all covers s	ecurely replaced? Yes	The Hote other (enter authorization c	ode) To Peo	P	
3. Is there evidence	of tank loakage from a ser	□ No				
evidence of dam	of tank leakage from a sep	tic, holding, pret	reatment or pump	tank below the oper	ating depth or	
	naged, cracked, or structura	ally unsound mair	itenance hole cove	ers? 🗌 Yes 🗌 No		
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	Yes No	☐ Ves ☐ No		
4. How many gallons	of septage were removed?		☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 1250	of septage were removed?gal Tank #2	gal Pretreatment	tank ga	J. Pump Tank		
Tank #1 1250	of septage were removed?gal Tank #2	gal Pretreatment	tank ga	J. Pump Tank	gal	
Tank #1 1250	of septage were removed?	gal Pretreatment	tank ga	J. Pump Tank	gal concerns.	
Tank #1 1250	of septage were removed?gal Tank #2	gal Pretreatment	tank ga	J. Pump Tank	gal concerns.	
Tank #1 1250	of septage were removed?gal Tank #2 : List any troubleshooting,	gal Pretreatment	tank ga	J. Pump Tank	gal concerns.	
Tank #1 /2 SD 5. Other information	of septage were removed?gal Tank #2 : List any troubleshooting,	gal Pretreatment	tank ga	J. Pump Tank	gal concerns.	
Tank #1 /2 SD 5. Other information	of septage were removed? gal Tank #2 : List any troubleshooting, e disposal:	gal Pretreatment minor repairs cor	tankganducted, tank safet	J. Pump Tank	gal concerns.	
Tank #1 /2 SD 5. Other information	of septage were removed? gal Tank #2 : List any troubleshooting, e disposal:	gal Pretreatment	tankganducted, tank safet	J. Pump Tank	gal concerns.	

Afton MN 55001