	roperty Address: 11625 LEEWARD AVE S, CITY OF COTTAGE GROVE usiness Name: SS Septic Solutions, LLC Date: 11/15/2021
3.	Other compliance conditions – Compliance component #3 of 5
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured? ☐ Yes ☑ No ☐ Unknown 3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety? ☐ Yes ☑ No ☐ Unknown "Yes to 3a or 3b - System is an imminent threat to public health and safety.
	3c. System is non-protective of ground water for other conditions as determined by inspector? □ Yes □ No 3d. System not abandoned in accordance with Minn. R. 7080.2500? □ Yes □ No □ Yes □ No □ Yes □ No □ Yes □ No □ System is failing to protect groundwater □ Describe verification methods and results:
1 .	Attached supporting documentation: ☐ Not applicable ☐ Operating permit and nitrogen BMP* — Compliance component #4 of 5 ☒ Not applicable
	Is the system operated under an Operating Permit?
	Attached supporting documentation: Operating permit (Attach)

https://www.pca.state.mn.us wq-wwists4-31b • 4/28/2021