,	compliance comp	Date: <u>11/</u> ponent #1 of 5	TO/LGE!
Compliance criteria:		Attached supporting documentation:	*****
System discharges sewage to the ground surface	☐ Yes* ⊠ No	☐ Other:	
System discharges sewage to drain tile or surface waters.	☐ Yes* ☒ No		
System causes sewage backup into dwelling or establishment.	☐ Yes* 🛛 No		
Any "yes" answer above indicates imminent threat to public health a			(3)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit,	e component #2 ☐ Yes* ☑ No	Attached supporting documentation: ☑ Empty tank(s) viewed by inspector	Mevers
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their		Attached supporting documentation:	Meyers 11/15/2021
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth?	☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business:	11/15/2021
System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance	11/15/2021) hree years) ent complies with