DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance 11/10/201 Reas	on for Maintenance:	56022 x 29	3651
Property Address: 1015% - 122	rd St.N. Pro	perty Owner's Name:	ithrow Elem Schoo
Municipality: Buga	State Zip Co	de GEO d	Code/Property I.D. #:
What was done to the system?	Tank M	easurements (must be c	ompleted if tanks NOT pumped)
Tank(s) Pumped	Liquid Lovel of T		
Sludge and scum measured.	Liquid Level of Ta	ank in. Sludge	Level in. Scum Level in.
Do tanks need to be pumped? Yes No (If no provide measurem)	Total (Sludge + S	cum) / Liquid Lo	evel = % Sludge & Scum
1. Access used to remove septage: Main			 * Tank must be pumped if this value is greater than 25%.
2. If maintenance hole was used, were all cov	ers securely replaced?	Yes No please exp	plain
Explanation:			
3. If owner refuses to allow a Subsurface So them complete and sign the following st	ewage Treatment Syste	m (SSTS) to be pumped	through the maintenance hole, have
hole Lundorstand that removed of callida	(owner's name), refuse to	allow the removal of sol	ids and liquids through the maintenance
hole. I understand that removal of solids ar			dered maintenance.
4. Is the tank designed as a leaky tank? examp		arywell, leaching pit	
Tank#1 Tyes No Verificatio Metho	od Used:	-	
Tank#2 Yes No Verificatio Metho	od Used:		
5. Is there evidence of tank leakage from a		tment or numn tank he	low the enquettion during
damaged, cracked, or structurally unsou	nd maintenance hole co	overs?	iow the operating depth or evidence of
Tank	Leaking Out	Leaking In	Cover Damage
Septic/Holding Tank #1	Yes No	Yes No	Yes KNo
Septic/Holding Tank #2	Yes No	Yes No	Yes Kino
Pretreatment Tank	Yes No	Yes No	☐Yes ☐No
Pump Tank	Yes No	Yes No	Yes No
5. How many gallons of septage were remo	ved?		
Tank#1 2750 Tank#2 274	Pretreatment Ta	ank Pi	ump Tank ///5-0
7. Other information: List any troubleshooti	ng, minor repairs cond	ucted, tank safety conce	orns or other conserve
	•		
Certification: I hereby certify as a State of M	Ainnesota certified SSTS	Maintainer that I nersona	lly conducted the work
and made the observations,	or directly supervised oth	ners in the performance o	f this job.
Maintainer's Name: Olson's Sewer Service, I	nc. Maintaine	er's Address: 17638 Lyons	Street NE, Forest Lake, MN
Maintainer's License #: 216 Mainta	niner's Phone #: 651-46	4-2082	
Maintainer's Signature	him	Date: //	1-16-21
	//		