## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintenance 1173 27 Reason	n for Maintenance:	01528 x 321	162
Property Address: 8500 Domen		perty Owner's Name:	patt cardwell
Municipality: Lake ELMO	State Zip Cod	de GEO Co	ode/Property I.D. #:
(What was done to the system?	Tank Me	asurements (must be co	mpleted if tanks NOT pumped)
Tank(s) Pumped	Liquid Level of Ta	rik in. Sludge	Level in. Scum Level in.
Sludge and scum measured.  Do tanks need to be pumped?			
Yes No (If no provide measureme	nts) Total (Sludge + So	cum) / Liquid Le	vel = % Sludge & Scum
1. Access used to remove septage: Mainto	enance Hole Other	(Go to #3 below)	* Tank must be pumped if this value is greater than 25%.
2. If maintenance hole was used, were all cover	rs securely replaced?	Yes 🔲 No <b>please exp</b>	_
Explanation:	,		
3. If owner refuses to allow a Subsurface Set them complete and sign the following sta	wage Treatment Syste tement:	m (SSTS) to be pumped t	through the maintenance hole, have
l, (e	owner's name), refuse to	allow the removal of soli	ds and liquids through the maintenance
hole. I understand that removal of solids and			
4. Is the tank designed as a leaky tank? example	e: seepage pit, cesspool, c	lrywell, leaching pit	
Tank#1 Yes No Verificatio Metho	d Used:		
Tank#2 Yes No Verificatio Metho	d Used:		
5. Is there evidence of tank leakage from a s	eptic, holding, pretrea	tment or pump tank bel	ow the operating depth or evidence of
damaged, cracked, or structurally unsoun		1	
Tank	Leaking Out	Leaking In	Cover Damage
Septic/Holding Tank #1	Yes No	Yes No	Yes
Septic/Holding Tank #2	Yes No	Yes No	Yes No
Pretreatment Tank Pump Tank	Yes No	Yes No	Yes No
6. How many gallons of septage were remov		Yes No	☐ Yes ☐ No
or moniment Assigns of Schrade Mete setting	eu:		
	1		
Tank #1 1550 Tank #2 1050	Pretreatment Ta	ankPL	ımp Tank
Tank #1 Tank #2			· · · · · · · · · · · · · · · · · · ·
7. Other information: List any troubleshootin	ng, minor repairs cond	ucted, tank safety conce	erns, or other concerns.
7. Other information: List any troubleshooting  8. Certification: I hereby certify as a State of N	ng, minor repairs cond linnesota certified SSTS or directly supervised ot	ucted, tank safety conce Maintainer that I personal ners in the performance o	erns, or other concerns.
7. Other information: List any troubleshooting 8. Certification: I hereby certify as a State of Mande the observations, of Maintainer's Name: Olson's Sewer Service, In	ng, minor repairs cond linnesota certified SSTS or directly supervised ot	Maintainer that I personal hers in the performance of er's Address: 17638 Lyons	lly conducted the work f this job.