

520 Lafayette Road North St. Paul, MN 55155-4194

Compliance inspection report form

Existing Subsurface Sewage Treatment System (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf.

Property information	Local tracking	number:
Parcel ID# or Sec/Twp/Range: 20.029.20.44.0026	Reason for Inspection	property sale
Local regulatory authority info: Washington County		
Property address: 2068 Novak Ave N Stillwater, MN 55082		4
Owner/representative: Juli Hagstrom, LaBelle Real Estate Gro	oup	Owner's phone: 651-303-1123
Brief system description: Two precast septic tanks and a rock to	rench drainfield.	
System status		
System status on date (mm/dd/yyyy): 11/22/2021		
☐ Compliant – Certificate of compliance*	☐ Noncompliant – Noti	ce of noncompliance
(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and	Systems failing to protect grouse discontinued within the t	ound water must be upgraded, replaced, or imme required by local ordinance.
abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)	An imminent threat to public	health and safety (ITPHS) must be
*Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.		se discontinued within ten months of receipt ter period if required by local ordinance or ivision 8.
Reason(s) for noncompliance (check all applicate	ole)	
☐ Impact on public health (Compliance component #1		health and safety
☐ Tank integrity (Compliance component #2) – Failing		
☐ Other Compliance Conditions (Compliance components)		public health and safety
☐ Other Compliance Conditions (Compliance components)	ent #3) – Failing to protect gi	roundwater
System not abandoned according to Minn. R. 7080.		nt #3) – Failing to protect groundwater
Soil separation (Compliance component #5) – Failin		
Operating permit/monitoring plan requirements (Cor	mpliance component #4) – N	oncompliant - local ordinance applies
Comments or recommendations		
Reviewed design, soil, permit & inspection records on file	e at Washington County.	
Certification		
I hereby certify that all the necessary information has been gathered future system performance has been nor can be made due to unknowinadequate maintenance, or future water usage.	to determine the compliance st wn conditions during system co	tatus of this system. No determination of onstruction, possible abuse of the system,
By typing my name below, I certify the above statements to be true used for the purpose of processing this form.	and correct, to the best of my	knowledge, and that this information can be
Business name: All State Septic Services LLC		Certification number: 323
Inspector signature:Tom Trooien		License number: 1568
(This document has been electronically sign	ned)	Phone: 612-594-4496
Necessary or locally required supporting do	cumentation (must b	ne attached)
	ouritaine (illast b	
Soil observation logs	equired forms	
☑ Soil observation logs☑ System/As-Built☑ Other information (list):		

Compliance criteria:		Attached supporting documentation:
System discharges sewage to the ground surface	☐ Yes* ☒ No	Other:
ground surface		☐ Not applicable
System discharges sewage to drain tile or surface waters.	☐ Yes* ☐ No	_
System causes sewage backup into dwelling or establishment.	☐ Yes* ☒ No	_
Any "yes" answer above indicates imminent threat to public health a	the system is an	
Describe verification methods and		-
		none observed during the inspection.
to see the state of the see that the see tha	ano ground surface -	none observed during the inspection.
ank integrity. Compliance		
ank integrity – Compliance	component #2	of 5
ank integrity – Compliance Compliance criteria:	component #2	of 5 Attached supporting documentation:
Compliance criteria: System consists of a seepage pit,	component #2	Attached supporting documentation:
Compliance criteria:	·	
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	·	Attached supporting documentation: Empty tank(s) viewed by inspector
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance:
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their	☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach)
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (See form instructions to ensure assessment complies with
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks:	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (See form instructions to ensure assessment complies with Minn. R. 7082.0700 subp. 4 B (1))
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (See form instructions to ensure assessment complies with Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessary – explain below
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic is failing to protect groundwate.	☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ates the system er.	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (See form instructions to ensure assessment complies with
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic	☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ates the system er.	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (See form instructions to ensure assessment complies with Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessary – explain below
Compliance criteria: System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit? Sewage tank(s) leak below their designed operating depth? If yes, which sewage tank(s) leaks: Any "yes" answer above indic is failing to protect groundwate.	☐ Yes* ☑ No ☐ Yes* ☑ No ☐ Yes* ☑ No ates the system er.	Attached supporting documentation: Empty tank(s) viewed by inspector Name of maintenance business: License number of maintenance business: Date of maintenance: Existing tank integrity assessment (Attach) Date of maintenance (mm/dd/yyyy): (See form instructions to ensure assessment complies with Minn. R. 7082.0700 subp. 4 B (1)) Tank is Noncompliant (pumping not necessary – explain below

Р	Property Address: 2068 Novak Ave N Stillwater, MN 55082	
В	Business Name: All State Septic Services LLC	Date: 11/22/2021
3.	3. Other compliance conditions – Compliance component #3 of 5	
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecu	ured?
	☐ Yes* ☐ No ☐ Unknown	il Cu :
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety?	☐ Yes* ☒ No ☐ Unknown
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.	
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes* ☒ No
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	☐ Yes* ☒ No
	*Yes to 3c or 3d - System is failing to protect groundwater.	
	Describe verification methods and results:	
	Attached supporting documentation: ⊠ Not applicable □	
	Treatment of the control of the cont	
_		
4.		5 ⊠ Not applicable
4.	. Operating permit and nitrogen BMP* – Compliance component #4 of !	
4.	ls the system operated under an Operating Permit? □ Yes ☑ No If "	'yes", A below is required
4.	. Operating permit and nitrogen BMP* – Compliance component #4 of !	'yes", A below is required
4.	Solution of the System operated under an Operating Permit? Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☒ No If the System required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☒ No If the System required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☒ No If the System required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☒ No If the System required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☒ No If the System required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☒ No If the System required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☒ No If the System required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☒ No If the System required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☒ No If the System required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☒ No If the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nitrogen BMP specified in the System required to employ a Nit	'yes", A below is required
4.	Is the system operated under an Operating Permit? Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☒ No If " BMP = Best Management Practice(s) specified in the system design	'yes", A below is required
4.	Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☒ No If " BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed.	'yes", A below is required
4.	Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed. Compliance criteria:	'yes", A below is required
4.	Is the system operated under an Operating Permit?	'yes", A below is required
4.	Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed. Compliance criteria: a. Have the operating permit requirements been met? BMP in place and properly functioning? Yes No	'yes", A below is required
4.	Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed. Compliance criteria: a. Have the operating permit requirements been met? b. Is the required nitrogen BMP in place and properly functioning? Yes No Any "no" answer indicates noncompliance.	'yes", A below is required
4.	Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed. Compliance criteria: a. Have the operating permit requirements been met? b. Is the required nitrogen BMP in place and properly functioning? Yes No Any "no" answer indicates noncompliance.	'yes", A below is required
4.	Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed. Compliance criteria: a. Have the operating permit requirements been met? b. Is the required nitrogen BMP in place and properly functioning? Yes No Any "no" answer indicates noncompliance.	'yes", A below is required
4.	Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed. Compliance criteria: a. Have the operating permit requirements been met? b. Is the required nitrogen BMP in place and properly functioning? Yes No Any "no" answer indicates noncompliance.	'yes", A below is required
4.	Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed. Compliance criteria: a. Have the operating permit requirements been met? b. Is the required nitrogen BMP in place and properly functioning? Yes No Any "no" answer indicates noncompliance.	'yes", A below is required
4.	Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed. Compliance criteria: a. Have the operating permit requirements been met? b. Is the required nitrogen BMP in place and properly functioning? Yes No Any "no" answer indicates noncompliance.	'yes", A below is required
4.	Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed. Compliance criteria: a. Have the operating permit requirements been met? b. Is the required nitrogen BMP in place and properly functioning? Yes No Any "no" answer indicates noncompliance.	'yes", A below is required
4.	Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed. Compliance criteria: a. Have the operating permit requirements been met? b. Is the required nitrogen BMP in place and properly functioning? Yes No Any "no" answer indicates noncompliance.	'yes", A below is required
4.	Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed. Compliance criteria: a. Have the operating permit requirements been met? b. Is the required nitrogen BMP in place and properly functioning? Yes No Any "no" answer indicates noncompliance.	'yes", A below is required

usiness Name: _ All State Septic Services LLC		Date: <u>11/22/2021</u>
Soil separation – Compliance cor	nponent #5 o	f 5
Date of installation 8/22/1991 (mm/dd/yyyy)	Unknown	
Shoreland/Wellhead protection/Food beverage lodging? Compliance criteria (select one):	☐ Yes ⊠ No	 Attached supporting documentation: ☑ Soil observation logs completed for the report ☐ Two previous verifications of required vertical separat
5a. For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:	⊠ Yes □ No*	☐ Not applicable (No soil treatment area)
Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.		
5b.Non-performance systems built April 1, 1996, or later or for non- performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment: Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*	☐ Yes ☐ No*	A. Bottom of distribution media 2.1 B. Periodically saturated soil/bedrock 4.5 C. System separation 2.4 D. Required compliance separation* 2 *May be reduced up to 15 percent if allowed by Local Ordinance.
5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License required ≤ 2,500 gallons per day; Advanced Inspector License required > 2,500 gallons per day) Drainfield meets the designed vertical	☐ Yes ☐ No*	
separation distance from periodically saturated soil or bedrock.		

Describe verification methods and results:

Upgrade requirements: (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

Soil Observation Log

				3
44			A	3
N. S.				
UNIVERSITY OF MINNESOTA	ONSITE	SEWAGE	TREATMENT	PROGRAM
~	US	2	111	ŏ

Project ID:

v 04.01.2021

Consistence 11/22/21 2068 Novak Ave N Stillwater, MN 55082 (Date) Elevation-relative to benchmark: |----- Structure------Limiting Layer Elevation: 11/22/21 Auger Organic Matter Grade Bedrock Date Observation Type: (License #) Shape 1568 Alluvium Location / Address: Indicator(s) hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws. Ē Slope shape Redox Kind(s) Loess Tom Trooien Soil survey map units: (Signature) Mottle Color(s) Slope %: Matrix Color(s) 10YR 3/2 7.5YR 4/4 10YR 5/4 Soil parent material(s): (Check all that apply) B-2 Rock Frag. % Weather Conditions/Time of Day: Landscape Position: (select one) (Designer/Inspector) Observation #/Location: sandy loam sandy loam loamy sand Texture Tom Trooien Vegetation: Comments Depth (in) 10-30 30-54 0-10 Client:

Soil Observation Log

v 04.01.2021

Project ID:

44			3
INNESOTA		MENT	AM
NIVERSITY OF MINNESOTA	ONSITE	TREATMENT	PROGRAM

Consistence 11/22/21 (Date) 2068 Novak Ave N Stillwater, MN 55082 Elevation-relative to benchmark: |------ Structure-------Limiting Layer Elevation: 11/22/21 Auger Organic Matter Grade Bedrock Date Observation Type: (License #) Shape 1568 Alluvium Location / Address: Indicator(s) hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws. E Slope shape Redox Kind(s) Loess Outwash Lacustrine Tom Trooien Soil survey map units: (Signature) Mottle Color(s) Slope %: Matrix Color(s) 10YR 3/2 10YR 4/4 10YR 4/6 Soil parent material(s): (Check all that apply) B-1 Frag. % Rock Weather Conditions/Time of Day: Landscape Position: (select one) (Designer/Inspector) Observation #/Location: carbonates sandy loam loamy sand w/calcium Texture Tom Trooien loam Comments Vegetation: Depth (in) 14-32 32-54 0-14 Client:

Company Company (Cont.) (Cont.)	State: MM	Parcel ID: Zip code: \$5082
A resident to the second of th	maner interpretation in the contract of the second distribution of the seco	EIP GOUE.
Optional section: Sewage Tank Compliance	Certification	The second secon
Total a complete and	The state of the s	
This form does not represent a complete system inspection Instructions: This section of the form may be completed and s Maintenance Business who personally conducts the necessary in the system. When this section of the form is signed by a qualified certified precising System Compliance Inspection Report: Compliance instruction on the MPCA website at https://www.pca.etate.mn.us/waterfree information and certified statement on this fee	ofessional, it becomes nece	ified Individual (DCI) of a licensed SST ompliance status of each sewage tank essary supporting documentation to an
The information and certified statement on this form is required individual other than the SSTS Inspector that submits the inspectomponent compliance and is allowable under Minn. R. 7082.070 equired according to local regulations. Additional Administrative R. 7082.070, subp. 4 Items B, C, and D: 7083.0720 feetings and D: 7083.0720 feetings.	when existing septic tank co tion report. It represents a t	ompliance status is determined by an
Certificate of sewage tank compliance Affirm all three statements: The SSTS does not contain a seepage pit, cesspool, drywell, leaching pit, or other pit. It does not contain a sewage tank that was designed to be watertight, but subsequently leaks below the designed operating depth. It does not represent an imminent safety threat by reason of unsecured, damaged, or weak maintenance hole cover(s) or other unsafe condition. Impany information Impany information Impany name: The SSTS does not contain a seepage pit, cesspool, drywell, leaching pit, or other pit. It does not represent an imminent safety threat by reason of unsecured, damaged, or weak maintenance hole cover(s) or other unsafe condition.	Select all that apply: The SSTS has leaching pit, or Groundwater. It has a sewag watertight, but operating depti the transfer of the transfe	a seepage pit, cesspool, drywell, other pit – "Failure to Protect" e tank that was designed to be subsequently leaks below the designe in – "Failure to Protect Groundwater." reat to public safety by reason of naged, or weak maintenance hole in unsafe condition – "Imminent Threath or Safety."
	Date (mm/dd/yyyy):	\\\2/2\

