

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain operite for the duration

	1/->// >/		<u> </u>	ion of the maintenance	e activity.
Date of Maintenance	-10-1	or Maintenance:	Keg Ma	n	,
Property Address:	185 Scandia TI	N	Property Owner's N	ame: Rod + Mary 1	Youder
Municipality: Fore	ZIP:5502	5 Property Ide	ntification Number:	:	
Maintenance Permit	No: 98979425693 M	aintainer Name a	nd License No. <u>Smil</u>	ie's Sewer Service/L24	128
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
☐ Tank(s) Pumped☐ Sludge and scum Do tanks need to ☐ Yes ☐ No (i	m measured Sludge Level in Tank in Scum Level in Tank				
1. Access used to re	emove septage: Maintenand	ce Hole 2 Other (e	enter authorization co	nde)	
evidence of dan	e of tank leakage from a sept naged, cracked, or structural Tank	ic, holding, preti lly unsound main ————————————————————————————————————	tenance hole cove Leaking In	rs? Yes And	ting depth or
	Septic/Holding Tank #1	☐ Yes ☑No	☐ Yes ☑No	☐ Yes ☐4No	
	Septic/Holding Tank #2	☐ Yes ♠No	☐ Yes ☐No	Yes And	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1	s of septage were removed? gal Tank #2 Occion n: List any troubleshooting, and the septage were removed?	gal Pretreatment	tank ganducted, tank safe	al Pump Tank ty concerns, or other	gal concerns.

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073 License# 2428 P: 651-433-3934