

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

prior to performing maintenance activiti	to constitute a v	alid maintenance	permit. This permit	must be completed
Date of Maintenance: 6-17-16 Reason	for Maintenance:	Dea An	ation of the maintena	nce activity.
			C 1	
Property Address: 1370 Quant P	Ive s	Property Owner's	Name: GOOW	Kircher
Municipality: Lakeland ZIP: 530	43 Property Ide	entification Numbe	er: <i>0</i>	
Maintenance Permit No: GH347871 M	aintainer Name a	nd License No. P	inky's Environmental Se	ewer Service/L1673
Maintenance Performed	Tank Mea	surement (must b	pe completed if tanks	NOT pumped)
Tank(s) Pumped	A STATE OF THE PARTY OF THE PAR	Tank i		
☐ Sludge and scum measured	Sludge Level in	Tank ii	n Scum Level in Tank.	in
Do tanks need to be pumped?	Sludge + Scum _	/ Liquid	Level X 100	
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Sc	um T	anks must be pumped	if 25% or greater
<ol> <li>Access used to remove septage:  Maintenance</li> <li>Were all covers securely replaced?  Yes </li> <li>Is there evidence of tank leakage from a septing evidence of damaged, cracked, or structural</li> </ol>	No	eatment or num	n tools below the	ating depth or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?				
Tank #1 / 2-57 gal Tank #2	al Pretreatment	tank	gal Pump Tank	gal
5. Other information: List any troubleshooting, n	ninor repairs con	ducted, tank saf	ety concerns, or other	concerns.

Maintenance activities must be reported to the Department within 90 days.