

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire	rety to constitute a val	id maintenance p	ermit. This permit	must be completed	
prior to performing maintenance ac	tivities and remain on	site for the durat	ion of the maintena	nce activity.	
Date of Maintenance: 6/18/16 Rea	/	/	A 1	/ 00	
Property Address: 11324-1487	hstN F	roperty Owner's N	ame: <u>fe-fe</u>	Schaffer	
Municipality: SHIIWate ZIP:	Property Ider	ntification Number	:	- 2428	
Maintenance Permit No: 1/5551k30	<u>∱</u> Maintainer Name ar	d License No. Sx	nilies Se	rue Seldic	
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped	Liquid Level of 7	Liquid Level of Tank in			
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?	tanks need to be pumped? Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greate					
<ol> <li>Access used to remove septage: Main</li> <li>Were all covers securely replaced?</li> <li>Is there evidence of tank leakage from a evidence of damaged, cracked, or structure.</li> </ol>	, Yes □ No a septic, holding, pretr	eatment or pump	tank below the ope	erating depth or	
Tank	Leaking Out	Leaking In	Cover Damage	-	
Septic/Holding Tank #1	☐ Yes ⋈o	☐ Yes 🗘 🕠	☐ Yes ☐No		
Septic/Holding Tank #2	☐ Yes ⋈No	☐ Yes ⊠No	□ Yes ⊠No		
Pretreatment Tank	☐ Yes ☐ Yo	☐ Yes 🕅	□ Yes ☑No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	_	
1					
4. How many gallons of septage were remo					
		t tankg	gal Pump Tank	700 gal	
4. How many gallons of septage were remore Tank #1 1000 gal Tank #2 1000 g	<u>රට</u> gal Pretreatmen				