

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed | | | | | |
|--|------------------------|--|------------|--------------|-----|
| prior to performing maintenance activities and remain on-site for the duration of the maintenance activity. | | | | | |
| Date of Maintenance: 6-17-16 Reason for Maintenance: Cleaning | | | | | |
| Property Address: 9657 75+4 5+ Property Owner's Name: Karen Rose | | | | | |
| Municipality: 54; llwsfer ZIP: 55082 Property Identification Number: | | | | | |
| Maintenance Permit No: <u>人 3039 z 2966</u> Maintainer Name and License No. Smilie's Sewer Service/L2428 | | | | | |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | | Liquid Level of Tank in | | | |
| Sludge and scum measured | | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to b | | Sludge + Scum / Liquid Level X 100 | | | |
| Yes 🗆 No (if r | = % Sludge & Scu | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| Access used to remove septage: Maintenance Hole Other (enter authorization code) No Manway Access Were all covers securely replaced? No System Pre 1978 Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? | | | | | |
| | Tank | Leaking Out | Leaking In | Cover Damage | |
| | Septic/Holding Tank #1 | ☐ Yes ☐No | ☐ Yes ☐No | ☐ Yes ☐ No | |
| | Septic/Holding Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| 4. How many gallons of septage were removed? | | | | | |
| Tank #1 gal Tank #2 gal Pretreatment tank gal Pump Tank gal | | | | | gal |
| 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns. | | | | | |
| | | | | | |
| 6. Location of septage disposal: | | | | | |