

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a val	id maintenance pe	ermit. This permit m	ust be completed
<u>prior</u> to perfor	ming maintenance activitie		1 - (1)	on of the maintenan	ce activity.
Date of Maintenance: _	6 2 1 16 Reason f	or Maintenance: _	eg	lacis	(I) = A (I
Property Address: 12	087 19674	57 N P	roperty Owner's N	ame: Veag K	ineteller
Municipality: Ma	rine ZIP:350	47Property Ider	ntification Number:	ş	
Maintenance Permit No	120001201		d License No5	,	8545
			perminensis dun amal englassi i ieleks		STOTE OF THE ORIGINAL PROPERTY OF THE ALLE OF THE
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers sec3. Is there evidence of	nove septage: Maintenan curely replaced? Yes [of tank leakage from a sep ged, cracked, or structura	□ No tic, holding, pretr	eatment or pump	tank below the oper	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes 🗖 No	☐ Yes ☐No	
	Septic/Holding Tank #2	\square Yes \square No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 /500 gal Tank #2		gal Pretreatmen	t tankg	gal Pump Tank	gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
		4			