

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| | completed in its entirety to | Constitute a vali | d manitenance per | init. This permit if | nust be completed |
|---|--|--|--|---|-------------------|
| prior to perform | ning maintenance activitie | s and remain on- | site for the duration | n of the maintenan | ce activity. |
| Date of Maintenance: | $\frac{5-2}{6}$ Reason for | or Maintenance: _ | Keg 17 | gry T | 0 1/ |
| Property Address: | 1543 ST C | aixtal P | roperty Owner's Nar | ne: Pyst | er Maes |
| Municipality: | /water ZIP:550 | Property Iden | tification Number: | | |
| Maintenance Permit No | :: <u>d618/x3084</u> m | aintainer Name an | d License No. 52 | milies | |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | | Liquid Level of Tank in | | | |
| Sludge and scum measured | | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? | | Sludge + Scum / Liquid Level X 100 | | | |
| ☐ Yes ☐ No (if no provide measurements) | | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| Were all covers see Is there evidence of | nove septage: Maintenan curely replaced? Yes of f tank leakage from a sept ged, cracked, or structura | ☐ No .ic, holding, pretr | eatment or pump to | ank below the oper | rating depth or |
| | | | | | |
| | Tank | Leaking Out | Leaking In | Cover Damage | |
| | Tank Septic/Holding Tank #1 | Leaking Out Yes No | Leaking In Yes No | Cover Damage Ves No | |
| | | 1/ | | 1 | |
| | Septic/Holding Tank #1 | ☐ Yes ☑No | ☐ Yes ☐ No | ☐ Yes No | |
| | Septic/Holding Tank #1 Septic/Holding Tank #2 | ☐ Yes ☐No☐ Yes ☐No | ☐ Yes ☑ No | ☐ Yes ☐No | |
| 4. How many gallons | Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank | ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No | ☐ Yes ☐ No ☐ Yes ☐ No | ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No | |
| Tank #1 | Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed? gal Tank #2 | ☐ Yes ☐ No gal Pretreatment | ☐ Yes ☐ No | ☐ Yes ☐ No | gal |
| Tank #1 | Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed? | ☐ Yes ☐ No gal Pretreatment | ☐ Yes ☐ No | ☐ Yes ☐ No | |