

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a	alid maintenance	permit This permit	
<u>prior</u> to performing maintenance activit	ies and remain o	n-site for the dur	ation of the maintena	nust be completed
Date of Maintenance: 6-28-16 Reason	for Maintenance:	Rustin	-	ice activity.
Property Address: 6485 Jasmine	Aven	Property Owner's	Name: Ven N	Phylonies
Municipality: Stillwork ZIP: 350	Property Id	entification Numbe	er:	<u>sersance</u>
Maintenance Permit No: <u>v3470 m 3139</u> M				ewer Service/L1673
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of Tank in			
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structura 	tic, holding, pret Illy unsound main	reatment or pump ntenance hole cov	p tank below the opera vers?	ating depth or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	Yes No	Yes No	☐ Yes ☐ No	
Septic/Holding Tank #2	Yes No	Yes 🗆 No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
. How many gallons of septage were removed?				
Tank #1 300 gal Tank #2	gal Pretreatmen	t tank g	gal Pump Tank	nal .
. Other information: List any troubleshooting,	minor repairs co	nducted, tank safe	ety concerns, or other	gal concerns.
Location of septage disposal:				

Maintenance activities must be reported to the Department within 90 days.