

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

		maintenance ner	mit. This permit mus	t be completed
This section must be completed in its entirety to	constitute a valid	to for the duratio	n of the maintenance	activity.
prior to performing maintenance activities	and remain on-s	te for the duratio	if of the mantenance	The second secon
Reason fo	r Maintenance:	100	Time	
Property Address: 4255 Twin Ct. Ma	Pr	operty Owner's Na	ne: Mild be	CCC
Municipality: Was Simo ZIP: 5504	2 Property Ident	ification Number:		-
Maintenance Permit No: WS965m168Ma	intainer Name and	License No.		
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
 ✓ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements) 	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
				but !
1. Access used to remove septage: Maintenance of the server securely replaced? Yes	ce Hole Other (e	nter authorization co	ide) swing se	on trak
2. Were all covers securely replaced? \square Yes \square	No		ope sep	ting dopth or
 Were all covers securely replaced:	ric holding pretr	eatment or pump tenance hole cove	rs?	tillig deptil of
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed	?	t tank	gal Pump Tank ety concerns, or othe	gal
1 - A Not Tank #2	Val Ficticating			

Maintenance activities must be reported to the Department within 90 days.