

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	oe completed in its entiret	y to constitute a	alid maintenance	permit This pormit	must be seemed a	
<u>prior</u> to perf	orming maintenance activ	ities and remain o	on-site for the dura	ation of the mainton	must be completed	
Date of Maintenance	e: <u>6-23-16</u> Reason	n for Maintenance	Row	tine	ince activity.	
Property Address: 12	535 Strawberr	4 Hill Rols	Property Owner's	Name: Toho	Klota	
Municipality: AF			entification Numbe		NIEDO	
Maintenance Permit	Mo: वुशेष्ट्रच्यादिष्टु:0M				ewer Service/L1673	
Mainten	ance Performed	Tank Mea	asurement (must b	e completed if tanks	NOT pumped)	
Tank(s) Pumped			Liquid Level of Tank in			
\square Sludge and scum measured		III	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to	be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (it	f no provide measurements)			anks must be pumped		
Is there evidence evidence of dam	of tank leakage from a sep paged, cracked, or structur	otic, holding, pret ally unsound mai	reatment or pump ntenance hole cove	tank below the operers?	rating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1 /500	gal Tank #2	gal Pretreatmen	t tank g	al Pump Tank	gal	
. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safe	ety concerns or othe	5ut	
menhoce	18 under patro				concerns.	
b. Location of septage	e disposal:					
- Location of septage	uispusat.					

Maintenance activities must be reported to the Department within 90 days.