Compliance criteria:		Attached supporting documentation:
System discharges sewage to the ground surface	☐ Yes* ⊠ No	☐ Other:
System discharges sewage to drain tile or surface waters.	☐ Yes* ⊠ No	
System causes sewage backup into dwelling or establishment.	☐ Yes* ☑ No	
Any "yes" answer above indicates imminent threat to public health a		
nk integrity — Compliance	component #2	of 5
<b>nk integrity</b> – Compliance Compliance criteria:	component #2	of 5 Attached supporting documentation:
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit,	component #2	Attached supporting documentation:  ⊠ Empty tank(s) viewed by inspector
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ☑ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  Meyers
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit,		Attached supporting documentation:  ⊠ Empty tank(s) viewed by inspector
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	☐ Yes* ☑ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their	☐ Yes* ☑ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  3/21/2022
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attach)  Date of maintenance
Compliance criteria:  System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?  Sewage tank(s) leak below their designed operating depth?  If yes, which sewage tank(s) leaks:  Any "yes" answer above indices.	☐ Yes* ☒ No ☐ Yes* ☒ No ☐ Yes* ☒ No	Attached supporting documentation:  Empty tank(s) viewed by inspector  Name of maintenance business:  License number of maintenance business:  Date of maintenance:  Existing tank integrity assessment (Attach)  Date of maintenance (mm/dd/yyyy):  (See form instructions to ensure assessment complies