



Client/ Address:		7889 Lamar Ave. S.		Legal Description/ GPS:		1202721330005	
Soil parent material(s): (Check all that apply)							
<input type="checkbox"/> Summit		<input type="checkbox"/> Shoulder		<input type="checkbox"/> Back/Side Slope		<input type="checkbox"/> Toe Slope	
<input type="checkbox"/> Outwash		<input type="checkbox"/> Lacustrine		<input checked="" type="checkbox"/> Loess		<input type="checkbox"/> Till	
<input type="checkbox"/> Alluvium		<input type="checkbox"/> Bedrock		<input type="checkbox"/> Organic Matter			
Landscape Position: (check one)				Slope shape			
Grass		Soil survey map units		49		Elevation:	
Weather Conditions/Time of Day:				Date			
40 degrees Cloudy				04/04/22			
Observation #/Location:				Observation Type:			
See Map				Auger			
Depth (in)	Texture	Rock Frag. %	Matrix Color(s)	Mottle Color(s)	Redox Kind(s)	Indicator(s)	Structure-----I
0-6"	Loam	<35%					Grade
7-28"	Loamy Sand	<35%	7.5YR 3/4				Consistence
29-60"	Coarse Sand	<35%	7.5YR 4/3				
Comments							
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.							
Shelley Schloimka				4137		4/4/2022	
(Designer/Inspector)				(License #)		(Date)	