



Project ID:

v 03.19.15

Client/ Address:		Bauer - 14740 113th Street South		Legal Description/ GPS:		3302720130006	
Soil parent material(s): (Check all that apply)							
<input checked="" type="checkbox"/> Outwash		<input type="checkbox"/> Lacustrine		<input type="checkbox"/> Loess		<input type="checkbox"/> Till	
<input type="checkbox"/> Summit		<input type="checkbox"/> Shoulder		<input checked="" type="checkbox"/> Back/Side Slope		<input type="checkbox"/> Foot Slope	
<input type="checkbox"/> Bedrock		<input type="checkbox"/> Alluvium		<input type="checkbox"/> Organic Matter			
Landscape Position: (check one)							
<input type="checkbox"/> Toe Slope		<input type="checkbox"/> Toe Slope		<input type="checkbox"/> Toe Slope		<input type="checkbox"/> Linear Linear	
Vegetation		Grass		Soil survey map units 411 & 411B		Elevation:	
Weather Conditions/Time of Day:		Sun 3:30 PM		Date		05/04/22	
Observation #/Location: See map							
Observation Type:		Auger					
Depth (in)		Texture		Rock Frag. %		Matrix Color(s)	
Mottle Color(s)		Redox Kind(s)		Indicator(s)		Shape	
Structure		Grade		Consistence			
0-11"		Silt Loam		<35%		10YR 3/4	
12" - 46"		Loamy Fine Sand		<35%		10YR 4/4	
47" - 60"		Sand		<35%		10YR 3/6	
Comments							
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.							
Shelley Schломka		4137		5/4/2022			
(Designer/Inspector)		(License #)		(Date)			

(Signature)