Р	roperty Address: 14740 113TH ST S, TOWN OF DENMARK	
	usiness Name: SS Septic Solutions, LLC	Date: <u>5/4/2022</u>
3.	Other compliance conditions – Compliance component #3 of 5	
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured?	
	☐ Yes* ☒ No ☐ Unknown	ourou.
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety	/? ☐ Yes* ☒ No ☐ Unknown
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.	
	3c. System is non-protective of ground water for other conditions as determined by inspector?	☐ Yes* ⊠ No
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	 □ Yes* ⊠ No
	*Yes to 3c or 3d - System is failing to protect groundwater.	
	Describe verification methods and results:	
	Attached supporting documentation: Not applicable	
4	Operating permit and nitragen BNAD* Compliance common ant #4.	6 F S7 N N N N N N N N N N
4.	Operating permit and nitrogen BMP* – Compliance component #4 o	Not applicable
	Is the system operated under an Operating Permit? ☐ Yes ☐ No ☐ I	f "yes", A below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? \square Yes \square No \square	f "yes", B below is required
	BMP = Best Management Practice(s) specified in the system design	
	If the answer to both questions is "no", this section does not need to be completed	l.
	Compliance criteria:	
	a. Have the operating permit requirements been met? ☐ Yes ☐ No	
	b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No	
	Any "no" answer indicates noncompliance.	
	Describe verification methods and results:	
	Attached supporting documentation: ☐ Operating permit (Attach) ☐	