

OSTP Soil Observation Log

Project ID: v 03.19.15

Client/ Address:		4142 Penfield Ave S Afton		Legal Description/ GPS:		2702820110002	
Soil parent material(s): (Check all that apply)							
<input type="checkbox"/> Outwash		<input type="checkbox"/> Lacustrine		<input type="checkbox"/> Loess		<input type="checkbox"/> Till	
<input type="checkbox"/> Summit		<input type="checkbox"/> Shoulder		<input type="checkbox"/> Foot Slope		<input type="checkbox"/> Toe Slope	
<input type="checkbox"/> Back/Side Slope		<input checked="" type="checkbox"/> Back/Side Slope		<input type="checkbox"/> Bedrock		<input type="checkbox"/> Organic Matter	
Landscape Position: (check one)				Slope shape			
Vegetation		Grass		Soil survey map units		529B	
Weather Conditions/Time of Day:				Date			
Observation #/Location:		See map		Observation Type:		Auger	
Depth (in)		Texture		Rock Frag. %		Matrix Color(s)	
0-12"		Silt Loam		<35%		10YR 3/3	
13" - 18"		Fill Soil		<35%		10YR 3/4	
Redox Kind(s)		Mottle Color(s)		Indicator(s)		Structure-----	
Shape		Grade		Consistence		Linear Linear	
Elevation:		Slope%		Date		05/24/22	
Comments							
I hereby certify that I have completed this work in accordance with all applicable ordinances, rules and laws.							
Shelley Schlomka		4137		5/24/2022			
(Designer/Inspector)		(License #)		(Date)			

Signature: 