

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed

Date of Maintenance: 5/11/22 Reason	for Maintenance:	A	IM A G H	C-Cl
3/10/01		, -	lame: Hugy n	K Ferst
200	Property Ide		01.00	· · · · · · ·
Maintenance Permit No: 40895 V 272			lie's Sewer Service/L2	2428
Maintenance Performed	Tank Mea	urement (must be	completed if tanks	NOT pumped)
☐ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements)	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintena	nce Hole Other (enter authorization c	ode)	
Were all covers securely replaced? Yes Is there evidence of tank leakage from a sequevidence of damaged, cracked, or structure Tank	otic, holding, pret	tenance hole cove	tank below the operers? Yes No	ating depth or
Septic/Holding Tank #1	☐ Yes 🛣 No	☐ Yes ☐ No	☐ Yes 🔼 No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed Tank #1 gal Tank #2	_ gal Pretreatmen			

Smilie's Sewer Service **PO BOX 100** Scandia, MN 55073 License# 2428 P: 651-433-3934

Maintenance activities must be reported to the Department within 90 days.