

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	/ / 74				The same of the sa	
	6 7 27 Reason f	or Maintenance: _	Keg Ma	int		
Property Address:	1533 Stoneb	ridge tol F	roperty Owner's N	ame: Charles + 1	Edith Peterson	
Municipality:	water ZIP:550	Property Idea	ntification Number:			
Maintenance Permit N	10: <u>CO597-27,5</u> 6ZM				 L2428	
	,					
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped		Liquid Level of 7	_iquid Level of Tank in			
Sludge Level in Tank in Scum Level in Ta					(in	
Do tanks need to I		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater				
	no provide measurements)					
1. Access used to ren	nove septage: Maintenand	ce Hole Other (e	nter authorization co	ode)		
	curely replaced? Yes		The addition action of	, (1)		
	of tank leakage from a sept		astment or nume	************************************		
	aged, cracked, or structura				erating depth or	
				is: Lies Zino	,	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes 🗷 No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes 🌠 No	☐ Yes ☐No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	The state of the s					
	Pump Tank of septage were removed?	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	gal	
Tank #1 700	Pump Tank of septage were removed?	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 700	of septage were removed? gal Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 700 5. Other information:	of septage were removed? gal Tank #2 200 : List any troubleshooting,	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Tank #1 700	of septage were removed? gal Tank #2 200 : List any troubleshooting,	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		

Smilie's Sewer Service PO BOX 100 Scandia, MN 55073

License# 2428 P: 651-433-3934