DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

SSTS MAINTENANCE REPORT

Date of Maintenance Reason	for Maintenance:	mpliance #	21519h	25/20	2
Property Address: 10257 - 15274	S}_ Prope	rty Owner's Name:			
Municipality: Dugo	State MN Zip Code	35038 G	EO Code/Property	y I.D. #:	
What was done to the system?	a e a ganikiMea	urements (must b	e completed if t	anksy@upunoea	
Tank(s) Pumped	Liquid Level of Tarif	in Ch.	dee Level	in. Scum Level	in.
Sludge and scum measured.	Liquid Level Of Tani	· m. siu	dge Level	- Scum Level	
Do tanks need to be pumped?	Total (Sludge + Scu	Total (Sludge + Scum) / Liquid Level = % Sludge			
Yes No (If no provide measurement			* Tank n	nust be pumped if th	nic value
1. Access used to remove septage: Maintel			is grea	ter than 25%.	iis value
2. If maintenance hole was used, were all covers	s securely replaced?	Yes No please	explain		
Explanation:					
3. If owner refuses to allow a Subsurface Sew them complete and sign the following state		(SSTS) to be pump	ed through the	maintenance hole	, have
I, (or	wner's name), refuse to a	llow the removal of	solids and liquid	ls through the main	enance
hole. I understand that removal of solids and			=		.c.iuiice
4. Is the tank designed as a leaky tank? example:	seepage pit, cesspool, dry	well, leaching pit			
Tank#1 Yes No Verificatio Method	Used: (1)				
					 -
Tank#2 Yes No Verificatio Method	Used:				
Is there evidence of tank leakage from a se damaged, cracked, or structurally unsound			below the oper	rating depth or evid	dence of
Tank	Leaking Out	Leaking In	Cover	Damage	
Septic/Holding Tank #1	Yes No	Yes No		-No	
Septic/Holding Tank #2	Yes No	☐ Yes ☐ No		□No	
Pretreatment Tank	Yes No	Yes No	Yes	No	
Pump Tank	Yes No	Yes No	Yes	□No	
6. How many gallons of septage were remove	d?				
Tank#1 /260 Tank#2	Pretreatment Tan	k	Pump Tank		
		0	-		
7. Other information: List any troubleshooting	g, minor repairs conduc	ted, tank safety co	oncerns, or othe	r concerns.	
8. Certification: I hereby certify as a State of Mi and made the observations, or				d the work	
Maintainer's Name: Olson's Sewer Service, Inc.	c. Maintainer'	s Address: 17638 Ly	yons Street NE, Fo	orest Lake, MN	
Maintainer's License #: 216 Maintair	ner's Phone #: 651-464-	2082			
Maintainer's Signature	8	Date:	6/6/22		
9			, ,		